

Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding a new AD to read as follows:

#### 95-08-13 B. Grob Flugzeugbau:

Amendment 39-9202; Docket No. 94-CE-30-AD.

**Applicability:** Model G109B gliders, serial numbers 6200 through 6445, certificated in any category.

**Note 1:** This AD applies to each glider identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For gliders that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (c) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any glider from the applicability of this AD.

**Compliance:** Required within the next 25 hours time-in-service after the effective date of this AD or within the next 6 calendar months after the effective date of this AD,

whichever occurs first, unless already accomplished.

To prevent failure of the elevator inner hinges because of delamination or corrosion, which, if not detected and corrected, could lead to loss of control of the glider, accomplish the following:

(a) Replace the elevator inner hinges (2) with hinges of improved design, part number 109B-3550, in accordance with Grob Repair Instructions No. 817-25 for Service Bulletin TM 817-25, dated November 9, 1987.

**Note 2:** The service instructions of this AD call for "the execution of the instructions to be certified in the log-book by an authorized inspector class 3." This type of inspector is not applicable in the United States and the person accomplishing the AD is as outlined in part 43 of the Federal Aviation Regulations (14 CFR part 43). This is not a change over normal AD procedures.

(b) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate gliders to a location where the requirements of this AD can be accomplished.

(c) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, Small Airplane Directorate, FAA, 1201 Walnut, suite 900, Kansas City, Missouri 64106. The request should be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Small Airplane Directorate.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Small Airplane Directorate.

(d) The replacement required by this AD shall be done in accordance with Grob Repair Instructions No. 817-25 for Service Bulletin TM 817-25, dated November 9, 1987. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from B. Grob Flugzeugbau, D-8939 Mattsies, Germany. Copies may be inspected at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment (39-9202) becomes effective on June 2, 1995.

Issued in Kansas City, Missouri, on April 11, 1995.

**Dwight A. Young,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 95-9342 Filed 4-21-95; 8:45 am]

**BILLING CODE 4910-13-U**

#### 14 CFR Part 39

[Docket No. 94-ANE-58; Amendment 39-9203; AD 95-08-14]

#### Airworthiness Directives; AlliedSignal, Inc. (Formerly Textron Lycoming) LTS101 Series Turboshaft Engines

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) that is applicable to AlliedSignal, Inc. (formerly Textron Lycoming) LTS101 series turboshaft engines. This action requires a one-time replacement of magnetic speed pickups in the engine electronic overspeed protection system, or inspection, and replacement, if necessary, of pickups with incorrect polarity. This amendment is prompted by reports of a manufacturing error that resulted in improper sensor polarity of magnetic speed pickups. The actions specified in this AD are intended to prevent the engine electronic overspeed protection system from failing to function as designed, which can result in the inability to arrest an uncontrolled power turbine (PT) rotor overspeed and damage to the aircraft.

**DATES:** Effective May 9, 1995.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 9, 1995.

Comments for inclusion in the Rules Docket must be received on or before June 23, 1995.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 94-ANE-58, 12 New England Executive Park, Burlington, MA 01803-5299.

The service information referenced in this AD may be obtained from AlliedSignal Engines, 550 Main Street, Stratford, CT 06497; telephone (203) 385-1470, fax (203) 385-2256. This information may be examined at the FAA, New England Region, Office of the Assistant Chief Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Eugene Triozzi, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (617) 238-7148, fax (617) 238-7199.