

arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 94-SW-15-AD." The postcard will be date stamped and returned to the commenter.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive (AD), Amendment 39-9148, to read as follows:

95-03-12 Schweizer Aircraft Corporation and Hughes Helicopters, Inc.:
Amendment 39-9148. Docket No. 94-SW-15-AD. Supersedes Priority Letter AD 93-03-01, issued on March 4, 1993.

Applicability: Model 269A, 269A-1, 269B, 269C, and TH-55A series helicopters, with aluminum spring retainer, part number (P/N) 269A5452, P/N 269A5452-3, P/N 269A5452-5, or P/N 269A5483-7, installed, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the aluminum spring retainer, loss of power to the rotor drive system, and a subsequent forced landing, accomplish the following:

(a) Within the next 5 hours time-in-service after the effective date of this AD, and thereafter at intervals not to exceed 100 hours time-in-service from the last inspection, visually inspect the clutch control spring assembly for component wear in accordance with the provisions of Part I, paragraph a(2) of Schweizer Service Bulletin (SB) B-256.2, dated June 11, 1993.

(b) If worn parts are found during the inspections accomplished in accordance with paragraph (a) of this AD, before the next flight, disassemble and inspect the clutch control spring assembly and replace parts found to be unairworthy with airworthy parts in accordance with Part I, paragraph b. of SB B-256.2, dated June 11, 1993.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used when approved by the Manager, New York Aircraft Certification Office, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, New York Aircraft Certification Office.

Note: Information concerning the existence of approved alternative methods of

compliance with this AD, if any, may be obtained from the New York Aircraft Certification Office.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the inspection requirements of this AD can be accomplished.

(e) The inspections and replacement, if necessary, shall be done in accordance with SB B-256.2, dated June 11, 1993. This incorporation by reference was approved previously by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51 as of September 1, 1994 (59 FR 38354, July 28, 1994). Copies may be obtained from Schweizer Aircraft Corporation, P.O. Box 147, Elmira, New York 14902. Copies may be inspected at the FAA, Office of the Assistant Chief Counsel, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on March 1, 1995.

Issued in Fort Worth, Texas, on February 6, 1995.

Eric Bries,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 95-3513 Filed 2-13-95; 8:45 am]

BILLING CODE 4910-13-P

14 CFR Part 39

[Docket No. 94-SW-21-AD; Amendment 39-9147; AD 95-03-11]

Airworthiness Directives; McDonnell Douglas Helicopter Systems and Hughes Helicopters, Inc. Model 369, OH-6A, and YOH-6A Series Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to McDonnell Douglas Helicopter Systems and Hughes Helicopters, Inc. Model 369, OH-6A, and YOH-6A series helicopters. This action requires initial and repetitive inspections of the tail rotor blade abrasion strip (abrasion strip), installation of stainless steel abrasion tape over the inboard end of the abrasion strip, and as a terminating action, installation of a tail rotor blade with a new-design abrasion strip. This amendment is prompted by several incidents of riveted abrasion strips debonding and separating during flight, resulting in severe out-of-balance conditions and subsequent separation of