



DE LOREAN MOTOR COMPANY

SERVICE BULLETIN

NUMBER ST-03-7/81

CATEGORY: TECHNICAL

ATTENTION: ALL DMC DEALERS/SERVICE MANAGERS

SUBJECT: STEERING RACK AND PINION ASSEMBLY-SERVICING

In the event the steering rack and pinion assembly requires unit repair, other than toe-in adjustment, the steering rack and pinion assembly must be replaced as a unit.

Please inform all personnel concerned.

Sincerely,

Lutz Feuerabendt
Technical Service Manager

ISSUED 7/1/81